



**Office of Environmental Public Health Sciences
Washington State Department of Health
243 Israel Road SE, Tumwater WA 98501**

Lead Sample Collection Information

DISCLAIMER: Results posted here only represent testing done by the Washington State Department of Health for the 2018-19 lead in school drinking water program. Schools have been provided these results, along with recommendations for remediation if applicable. Please contact your school to find out more about this and other testing they may have done, as well as plans for remediation.

School Name: Star Lake Elementary

School Code: 3160

School District Name: Federal Way

Address: 4014 S 270th St, Kent, WA 98032

County: King

Number of Samples Collected: 50

Date Collected: 05/22/2018

Sample number	Sample ID	Sample Type	Fixture Description	Fixture Location	Lead Content (ppb)	Date of Analysis	Notes/Comments
1.	9541	First Draw	Bubbler	Room 101	2	09/07/2018	
2.	9542	First Draw	Tap	Room 101	5	09/07/2018	
3.	9543	First Draw	Bubbler	Room 102	2	09/07/2018	
4.	9544	First Draw	Tap	Room 102	17	09/07/2018	
5.	9545	First Draw	Bubble	Room 103	4	09/07/2018	Tap in room is non-working
6.	9546	First Draw	Bubbler	Room 104	2	09/07/2018	
7.	9547	First Draw	Tap	Room 104	1	09/07/2018	
8.	9548	First Draw	Tap	Room 104	3	09/07/2018	Regular sink on right
9.	9549	First Draw	Bubbler	Room 105	<1	09/07/2018	
10.	9550	First Draw	Tap	Room 105	5	09/07/2018	No aerator
11.	9551	First Draw	Bubbler	Room 106	<1	09/07/2018	
12.	9552	First Draw	Tap	Room 106	1	09/07/2018	
13.	9553	First Draw	Bubbler	Room 107	<1	09/07/2018	
14.	9554	First Draw	Tap	Room 107	3	09/07/2018	
15.	9555	First Draw	Bubbler	Room 108	<1	09/07/2018	
16.	9556	First Draw	Tap	Room 108	<1	09/07/2018	
17.	9557	First Draw	Bubbler	Room 109	1	09/07/2018	
18.	9558	First Draw	Tap	Room 109	16	09/07/2018	
19.	9559	First Draw	Bubbler	Room 110	1	09/07/2018	

Sample number	Sample ID	Sample Type	Fixture Description	Fixture Location	Lead Content (ppb)	Date of Analysis	Notes/Comments
20.	9560	First Draw	Tap	Room 110	6	09/07/2018	
21.	9561	First Draw	Bubbler	Room 111	1	09/07/2018	
22.	9562	First Draw	Tap	Room 111	9	09/07/2018	
23.	9563	First Draw	Bubbler	Down hall from Room 111, near restrooms	<1	09/07/2018	
24.	9564	First Draw	Tap	Nurse's Office	5	09/07/2018	
25.	9565	First Draw	Tap	PT Room	33	09/07/2018	
26.	9566	First Draw	Bubbler	Room 112	4	09/07/2018	
27.	9567	First Draw	Tap	Room 112	4	09/07/2018	No aerator
28.	9568	First Draw	Bubbler	Room 113	1	09/07/2018	
29.	9569	First Draw	Tap	Room 113	7	09/07/2018	
30.	9570	First Draw	Bubbler	Room 114	3	09/07/2018	
31.	9571	First Draw	Tap	Room 114	3	09/07/2018	
32.	9572	First Draw	Bubbler	Room 116	<1	08/15/2018	
33.	9573	First Draw	Tap	Room 116	5	09/07/2018	Tap used
34.	9574	First Draw	Bubbler	Room 117	<1	09/07/2018	
35.	9575	First Draw	Tap	Room 117	4	09/07/2018	No aerator
36.	9576	First Draw	Bubbler	Room 118	4	09/07/2018	
37.	9577	First Draw	Tap	Room 118	4	09/07/2018	No aerator
38.	9578	First Draw	Bubbler	Room 119	1	09/07/2018	

Sample number	Sample ID	Sample Type	Fixture Description	Fixture Location	Lead Content (ppb)	Date of Analysis	Notes/Comments
39.	9579	First Draw	Tap	Room 119	9	09/07/2018	
40.	9580	First Draw	Bubbler	Room 120	3	09/07/2018	
41.	9581	First Draw	Tap	Room 120	1	09/07/2018	No aerator
42.	9582	First Draw	Bubbler	Room 121	<1	09/07/2018	
43.	9583	First Draw	Tap	Room 121	<1	09/07/2018	
44.	9584	First Draw	Bubbler	Room 122	1	09/07/2018	
45.	9585	First Draw	Tap	Room 121	1	09/07/2018	
46.	9586	First Draw	Bubbler	Room 115	<1	09/07/2018	
47.	9587	First Draw	Tap	Room 115	5	09/07/2018	
48.	9588	First Draw	Bubbler	Room 123	1	09/07/2018	
49.	9589	First Draw	Tap	Room 123	1	09/07/2018	
50.	9590	Blank		Near entrance	<1	09/07/2018	05902