



Lead Sample Collection Information

DISCLAIMER: Results posted here only represent testing done by the Washington State Department of Health for the 2018-19 lead in school drinking water program. Schools have been provided these results, along with recommendations for remediation if applicable. Please contact your school to find out more about this and other testing they may have done, as well as plans for remediation.

Please note: The school has since been renovated and all new lead free fixtures installed. The school is continuing to follow recommendations to reduce children's exposure to lead.

School District Name: White River Educational Service Center

School Name: Elkridge Elementary

School Code: 2190

Address: 27515 120th Ave E Buckley, WA 98321

County: Pierce

Number of Samples Collected: 44

Date Collected: 3/1/2018

Sample number	Sample ID	Sample Type	Fixture Description	Fixture Location	Lead Content (ppb)	Date of Analysis	Notes/Comments
Sample 1	1328	Initial Test	Sink Tap	Health Room	7	3/29/2018	
Sample 2	1327	Initial Test	Sink Tap	Room 201	13	3/29/2018	No aerator
Sample 3	1329	Initial Test	Sink Tap	Room 103	2	3/29/2018	
Sample 4	1330	Initial Test	Bubbler	Room 103	4	3/29/2018	
Sample 5	1331	Initial Test	Sink Tap	Room 102	13	3/29/2018	
Sample 6	1332	Initial Test	Bubbler	Room 102	4	3/29/2018	
Sample 7	1333	Initial Test	Sink Tap	Room 101	7	3/29/2018	
Sample 8	1334	Initial Test	Bubbler	Room 101	3	3/29/2018	
Sample 9	1335	Initial Test	Sink Tap	Room 100	7	3/29/2018	Bubbler not working
Sample 10	1336	Initial Test	Sink Tap	Room 104	11	3/29/2018	No aerator, Type:Chicago
Sample 11	1337	Initial Test	Bubbler	Room 104	4	3/29/2018	Type:Chicago
Sample 12	1338	Initial Test	Sink Tap	Room 105	10	3/30/2018	Soft-Flo Aerator
Sample 13	1339	Initial Test	Bubbler	Room 105	2	3/30/2018	
Sample 14	1340	Initial Test	Sink Tap	Room 106	20	3/30/2018	

Sample number	Sample ID	Sample Type	Fixture Description	Fixture Location	Lead Content (ppb)	Date of Analysis	Notes/Comments
Sample 15	1341	Initial Test	Bubbler	Room 106	4	3/30/2018	
Sample 16	1342	Initial Test	Sink Tap	Room 107	16	3/30/2018	
Sample 17	1343	Initial Test	Bubbler	Room 107	9	3/30/2018	
Sample 18	1344	Initial Test	Drinking Fountain	Main Hallway, Across from Gym	4	3/30/2018	Type:Elkay
Sample 19	1345	Initial Test	Drinking Fountain	Northwest Hallway by Kitchen	1	3/30/2018	
Sample 20	1346	Initial Test	Sprayer (by itself)	Kitchen	1	3/30/2018	
Sample 21	1347	Initial Test	Far Left Sink	Kitchen,	3	3/30/2018	
Sample 22	1348	Initial Test	Rinse-sanitize sink	Kitchen, middle sink	24	3/30/2018	
Sample 23	1349	Initial Test	Wash Sink	Kitchen, Far Right Sink	35	8/1/2018	
Sample 24	1350	Initial Test	Sink Tap	Room 119	4	3/30/2018	
Sample 25	1351	Initial Test	Bubbler	Room 119	2	3/30/2018	
Sample 26	1352	Initial Test	Sink Tap	Room 118	5	3/30/2018	
Sample 27	1353	Initial Test	Bubbler	Room 118	4	3/30/2018	
Sample 28	1354	Initial Test	Sink Tap	Room 117	27	3/30/2018	
Sample 29	1355	Initial Test	Bubbler	Room 117	2	3/30/2018	

Sample number	Sample ID	Sample Type	Fixture Description	Fixture Location	Lead Content (ppb)	Date of Analysis	Notes/Comments
Sample 30	1356	Initial Test	Sink Tap	Room 113	8	3/30/2018	
Sample 31	1357	Initial Test	Bubbler	Room 113	3	3/30/2018	
Sample 32	1358	Initial Test	Bubbler	Room 112	3	3/30/2018	
Sample 33	1359	Initial Test	Sink Tap	Room 111	30	3/30/2018	
Sample 34	1360	Initial Test	Bubbler	Room 111	5	3/30/2018	
Sample 35	1361	Initial Test	Sink Tap	Room 110	7	3/30/2018	
Sample 36	1362	Initial Test	Bubbler	Room 110	14	3/30/2018	
Sample 37	1363	Initial Test	Sink Tap	Room 114	13	3/30/2018	
Sample 38	1364	Initial Test	Sink Tap	Room 115	18	3/30/2018	
Sample 39	1365	Initial Test	Bubbler	Room 115	1	3/30/2018	
Sample 40	1366	Initial Test	Sink Tap	Room 116	5	3/30/2018	
Sample 41	1367	Initial Test	Bubbler	Room 116	3	3/30/2018	
Sample 42	1368	Initial Test	Blank	Hallway outside of 116	<1	3/30/2018	
Sample 43	1369	Initial Test	Sink Tap	Bathroom in portable, 183	<1	3/30/2018	Fountain not used, bathroom sinks may be used

Sample number	Sample ID	Sample Type	Fixture Description	Fixture Location	Lead Content (ppb)	Date of Analysis	Notes/Comments
Sample 44	1370	Initial Test	Sink Tap	Bathroom in portable, 184	<1	3/30/2018	Fountain not used, bathroom sinks may be used
					Notes:	Audio-Visual Room not tested and drinking water fountain in portable is not in use, couldn't take a sink tap sample from Rm. 112	