



Office of Environmental Public Health Sciences
Washington State Department of Health
243 Israel Road Southeast, Tumwater Washington 98501

Lead Sample Collection Information

DISCLAIMER: Results posted here only represent testing done by the Washington State Department of Health for the 2018-19 lead in school drinking water program. Schools have been provided these results, along with recommendations for remediation if applicable. Please contact your school to find out more about this and other testing they may have done, as well as plans for remediation.

Please Note: The school has participated in follow up testing and recommended remediation to help reduce children's exposure to lead in drinking water.

School District: FederalWay

School Name: Silver Lake Elementary

School Code: 4343

School Address: 1310 Southwest 325th Pl , Federal Way Washington 98023

Number of Samples Collected: 56

Date Collected: 04/24/2019

Program ID	Sample Type	Description	Location	Lead Results (ppb)	Analysis Date	Comments
23115	other	other		<1	05/03/2019	6:42 AM, 02583
23116	FirstDraw	Tap	Family Liaison Room	2	05/03/2019	
23117	FirstDraw	Tap	Health Room	<1	05/03/2019	
23118	FirstDraw	Tap	Staff Lounge	<1	05/03/2019	
23119	FirstDraw	Tap	Staff Lounge	<1	05/03/2019	
23120	FirstDraw	Tap	Staff Workroom	TB	NA	
23121	FirstDraw	Bubbler	Room 102	1	05/03/2019	
23122	FirstDraw	Tap	Room 102	<1	05/03/2019	
23123	FirstDraw	Bubbler	Room 104	<1	05/03/2019	
23124	FirstDraw	Tap	Room 104	1	05/03/2019	
23125	FirstDraw	Bubbler	Room 106	<1	05/03/2019	
23126	FirstDraw	Tap	Room 106	<1	05/03/2019	
23127	FirstDraw	Bubbler	Room 108	1	05/03/2019	
23128	FirstDraw	Tap	Room 108	1	05/03/2019	Tap drips
23129	FirstDraw	Bubbler	Room 110	<1	05/03/2019	
23130	FirstDraw	Tap	Room 110	<1	05/03/2019	
23131	FirstDraw	Bubbler	Room 112	1	05/03/2019	Some mineral deposits on body of bubbler
23132	FirstDraw	Tap	Room 112	1	05/03/2019	
23133	FirstDraw	Bubbler	Room 111	<1	05/03/2019	
23134	FirstDraw	Tap	Room 111	1	05/03/2019	
23135	FirstDraw	Bubbler	Room 109	<1	05/03/2019	Some mineral deposits on body of bubbler
23136	FirstDraw	Tap	Room 109	<1	05/03/2019	
23137	FirstDraw	Bubbler	Room 107	<1	05/03/2019	
23138	FirstDraw	Tap	Room 107	1	05/03/2019	

(continued)

Program ID	Sample Type	Description	Location	Lead Results (ppb)	Analysis Date	Comments
23139	FirstDraw	Bubbler	Room 105	1	05/03/2019	Some mineral deposits on bubbler
23140	FirstDraw	Tap	Room 105	<1	05/03/2019	Tap drips
23141	FirstDraw	Bubbler	Room 103	<1	05/03/2019	Mineral deposits on bubbler
23142	FirstDraw	Tap	Room 103	1	05/03/2019	
23143	FirstDraw	Bubbler	Room 101, Music Room	<1	05/03/2019	Mineral deposits on body and base of bubbler
23144	FirstDraw	Tap	Room 101, Music Room	2	05/03/2019	No aerator
23145	FirstDraw	Tap	Office in Library	4	05/03/2019	
23146	FirstDraw	Bubbler	Gym, South Side	11	05/03/2019	Barely able to fill a bottle due to low flow
23147	FirstDraw	Bubbler	Gym, North Side	<1	05/03/2019	
23148	FirstDraw	Bubbler	Cafeteria	1	05/03/2019	
23149	FirstDraw	Bubbler	Room 206	<1	05/03/2019	Used this morning
23150	FirstDraw	Tap	Room 206	1	05/03/2019	Used this morning
23151	FirstDraw	Bubbler	Room 208	<1	05/03/2019	Mineral deposits on body of bubbler
23152	FirstDraw	Tap	Room 208	<1	05/03/2019	
23153	FirstDraw	Bubbler	Room 210	<1	05/03/2019	Used this morning
23154	FirstDraw	Tap	Room 210	<1	05/03/2019	Used this morning
23155	FirstDraw	Bubbler	Room 212	<1	05/03/2019	
23156	FirstDraw	Tap	Room 212	<1	05/03/2019	Tap drips

(continued)

Program ID	Sample Type	Description	Location	Lead Results (ppb)	Analysis Date	Comments
23157	FirstDraw	Bubbler	Room 213	<1	05/03/2019	Mineral deposits on body of bubbler
23158	FirstDraw	Tap	Room 213	<1	05/03/2019	
23159	FirstDraw	Bubbler	Room 211	<1	05/03/2019	
23160	FirstDraw	Tap	Room 211	<1	05/03/2019	
23161	FirstDraw	Bubbler	Room 209	<1	05/03/2019	Some mineral deposits on body of bubbler
23162	FirstDraw	Tap	Room 209	<1	05/03/2019	
23163	FirstDraw	Bubbler	Room 205	<1	05/03/2019	Some mineral deposits near spout
23164	FirstDraw	Tap	Room 205	1	05/03/2019	
23165	FirstDraw	Bubbler	Room 207	1	05/03/2019	Used this morning
23166	FirstDraw	Tap	Room 207	<1	05/03/2019	Used this morning
23167	FirstDraw	Bubbler	Room 203	1	05/03/2019	Mineral deposits on body of bubbler
23168	FirstDraw	Tap	Room 203	1	05/03/2019	
23169	FirstDraw	Bubbler	Room 202	<1	05/03/2019	
23170	FirstDraw	Tap	Room 202	1	05/03/2019	