



Office of Environmental Public Health Sciences
Washington State Department of Health
243 Israel Road Southeast, Tumwater Washington 98501

Lead Sample Collection Information

DISCLAIMER: Results posted here only represent testing done by the Washington State Department of Health for the 2018-19 lead in school drinking water program. Schools have been provided these results, along with recommendations for remediation if applicable. Please contact your school to find out more about this and other testing they may have done, as well as plans for remediation.

Please Note: The school is following all recommended remediation to help reduce children's exposure to lead in drinking water.

School District: Kent

School Name: Meadow Ridge Elementary

School Code: 4465

School Address: 27710 108th Ave Southeast, Kent Washington 98030

Number of Samples Collected: 71

Date Collected: 03/19/2019

Program ID	Sample Type	Description	Location	Lead Results (ppb)	Analysis Date	Comments
20723	other	other		<1	03/28/2019	02581, 6:50 AM
20724	FirstDraw	Tap	Main Office	7	03/28/2019	
20725	FirstDraw	Tap	Nurses Office	3	03/28/2019	
20726	FirstDraw	Tap	Staff Lounge	5	03/28/2019	
20727	FirstDraw	Tap	Staff Workroom	19	03/28/2019	
20728	FirstDraw	Bubbler	Room E101	<1	03/28/2019	
20729	FirstDraw	Tap	Room E101	7	03/28/2019	
20730	FirstDraw	Bubbler	Room E103	<1	03/28/2019	
20731	FirstDraw	Tap	Room E103	11	03/28/2019	
20732	FirstDraw	Bubbler	Room E105	<1	03/28/2019	
20733	FirstDraw	Tap	Room E105	12	03/28/2019	Low flow
20734	FirstDraw	Bubbler	Room E106	<1	03/28/2019	
20735	FirstDraw	Tap	Room E106	8	03/28/2019	
20736	FirstDraw	Bubbler	Room E104	<1	03/28/2019	
20737	FirstDraw	Tap	Room E104	16	03/28/2019	
20738	FirstDraw	Bubbler	Room E102	<1	03/28/2019	Some calcification on bubbler
20739	FirstDraw	Tap	Room E102	7	03/28/2019	
20740	FirstDraw	WaterCooler	Technology Center	<1	03/28/2019	
20741	FirstDraw	Bubbler	Room S201	<1	03/28/2019	
20742	FirstDraw	Tap	Room S201	13	03/28/2019	
20743	FirstDraw	Bubbler	Room S203	<1	03/28/2019	
20744	FirstDraw	Tap	Room S203	12	03/28/2019	
20745	FirstDraw	Bubbler	Room S205	<1	03/28/2019	
20746	FirstDraw	Tap	Room S205	7	03/28/2019	
20747	FirstDraw	Bubbler	Room S207	<1	03/28/2019	
20748	FirstDraw	Tap	Room S207	7	03/28/2019	
20749	FirstDraw	Bubbler	Room S208	<1	03/28/2019	
20750	FirstDraw	Tap	Room S208	9	03/28/2019	
20751	FirstDraw	Bubbler	Room S206	<1	03/28/2019	
20752	FirstDraw	Tap	Room S206	19	03/28/2019	

(continued)

Program ID	Sample Type	Description	Location	Lead Results (ppb)	Analysis Date	Comments
20753	FirstDraw	Bubbler	Room S204	2	03/28/2019	
20754	FirstDraw	Tap	Room S204	15	03/28/2019	
20755	FirstDraw	Bubbler	Room S202	<1	03/28/2019	Used this morning
20756	FirstDraw	Tap	Room S202	17	03/28/2019	Used this morning
20757	FirstDraw	Bubbler	Physical Therapy Room Across from Media Center	1	05/28/2019	
20758	FirstDraw	Tap	Physical Therapy Room Across From Media Center	23	03/28/2019	Covered by orange bin, white gunk around Aerator
20759	FirstDraw	Bubbler	Room W301	2	03/28/2019	Calcification around mouth
20760	FirstDraw	Tap	Room W301	14	03/28/2019	
20761	FirstDraw	Bubbler	Room W303	<1	03/28/2019	Blue Paint near mouth
20762	FirstDraw	Tap	Room W303	7	03/28/2019	
20763	FirstDraw	Bubbler	Room W305	<1	03/28/2019	
20764	FirstDraw	Tap	Room W305	13	03/28/2019	
20765	FirstDraw	Bubbler	Room W307, East Side of Room	<1	03/28/2019	Fixtures are on, but class has not used for several days

(continued)

Program ID	Sample Type	Description	Location	Lead Results (ppb)	Analysis Date	Comments
20766	FirstDraw	Tap	Room W307, East Side of Room	7	03/28/2019	Fixtures are on, but class has not used for several days
20767	FirstDraw	Bubbler	Room W307, West Side of Room	1	03/28/2019	Water run this morning, dark rust or dirt on mouth
20768	FirstDraw	Tap	Room W307, West Side of Room	1	03/28/2019	Water used this morning
20769	FirstDraw	Tap	Room W309, East Side of Room	3	03/28/2019	
20770	FirstDraw	Bubbler	Room W309, West Side of Room	1	03/28/2019	
20771	FirstDraw	Tap	Room W309, West Side of Room	13	03/28/2019	
20772	FirstDraw	Bubbler	Room W308	5	03/28/2019	
20773	FirstDraw	Tap	Room W308	6	03/28/2019	
20774	FirstDraw	Bubbler	Room W306	<1	03/28/2019	
20775	FirstDraw	Tap	Room W306	12	03/28/2019	
20776	FirstDraw	Bubbler	Room W304	<1	03/28/2019	
20777	FirstDraw	Tap	Room W304	6	03/28/2019	
20778	FirstDraw	Bubbler	Room W302	<1	03/28/2019	
20779	FirstDraw	Tap	Room W302	7	03/28/2019	

(continued)

Program ID	Sample Type	Description	Location	Lead Results (ppb)	Analysis Date	Comments
20780	FirstDraw	Tap	Library	27	03/28/2019	Room behind counter
20781	FirstDraw	Bubbler	ELL Commons	2	03/28/2019	South Wall, Sink on Left, Low Flow
20782	FirstDraw	Tap	ELL Commons	3	03/29/2019	South Wall, Sink on Left
20783	FirstDraw	Bubbler	ELL Comons	<1	03/29/2019	South Wall, Sink on Right, Used this morning
20784	FirstDraw	Tap	ELL Commons	11	05/28/2019	South Wall, Sink on Right, Used this morning
20785	FirstDraw	WaterCooler	Portable 405	<1	03/29/2019	Broken Lever
20786	FirstDraw	WaterCooler	Portable 406	<1	03/29/2019	Near Empty
20787	FirstDraw	WaterCooler	Portable 407	<1	03/29/2019	
20788	FirstDraw	Bubbler	Gym, East Side	<1	03/29/2019	Used this Morning
20850	FirstDraw	Bubbler	Gym, West Side	<1	03/29/2019	Used this morning
20851	FirstDraw	Bubbler	Outside Cafeteria	<1	03/29/2019	Left Bubbler
20852	FirstDraw	Bubbler	Outside Cafeteria	<1	03/29/2019	Right Bubbler
20853	FirstDraw	Bubbler	Music Room	1	03/29/2019	
20854	FirstDraw	Tap	Music Room	17	03/29/2019	