



Office of Environmental Public Health Sciences
Washington State Department of Health
243 Israel Road Southeast, Tumwater Washington 98501

Lead Sample Collection Information

DISCLAIMER: Results posted here only represent testing done by the Washington State Department of Health for the 2018-19 lead in school drinking water program. Schools have been provided these results, along with recommendations for remediation if applicable. Please contact your school to find out more about this and other testing they may have done, as well as plans for remediation.

Please Note: The school is following recommended remediation to help reduce children's exposure to lead in drinking water. The school was sampled on two separate days due to its size and to ensure testing in compliance with EPA 3ts.

School District: FederalWay

School Name: Todd Beamer High School

School Code: 4570

School Address: 35999 16th Ave S, Federal Way Washington 98003

Number of Samples Collected: 59

Date Collected: 12/11/2019

Program ID	Sample Type	Description	Location	Lead Results (ppb)	Analysis Date	Comments
29387	other			<1	12/26/2019	
29388	FirstDraw	Bubbler	Hall bubblers across from gym entrance near room 290: high	1	12/26/2019	
29389	FirstDraw	Bubbler	Hall bubblers near rm 282A: low	<1	12/26/2019	
29390	FirstDraw	Bubbler	Hall bubblers near rm 270C (men restroom): low	<1	12/26/2019	
29391	FirstDraw	Bubbler	Hall bubblers next to rm 272E: low	<1	12/26/2019	
29392	FirstDraw	Bubbler	Hall bubblers next to rm 272E: high	<1	12/26/2019	
29393	FirstDraw	Bubbler	Hall bubblers next to snack bar: low	<1	12/26/2019	
29394	FirstDraw	Bubbler	Hall bubblers next to snack bar: high	<1	12/26/2019	
29395	FirstDraw	Tap	Rm 273 choir room	4	12/26/2019	
29396	FirstDraw	Tap	Rm 274 band room	1	12/26/2019	
29397	FirstDraw	Tap	Rm 282	1	12/26/2019	
29398	FirstDraw	Tap	Rm 290: weight room	1	12/26/2019	

(continued)

Program ID	Sample Type	Description	Location	Lead Results (ppb)	Analysis Date	Comments
29399	FirstDraw	Tap	Rm 200P staff workroom	1	12/26/2019	
29400	FirstDraw	Tap	Nurse office	2	12/26/2019	
29401	FirstDraw	Tap	Kitchen single sink	3	12/26/2019	For produce wash
29402	FirstDraw	Tap	Kitchen triple sink right	2	12/26/2019	
29403	FirstDraw	Tap	Kitchen triple sink left	8	12/24/2019	
29404	FirstDraw	Tap	Snack bar	1	12/26/2019	
29405	FirstDraw	Tap	Rm 204/staff room	3	12/26/2019	
29406	FirstDraw	Tap	Rm 210 sink on right wall looking towards window from rm 210A: right side	2	12/26/2019	
29407	FirstDraw	Tap	Rm 210 wall with front window: right tap	5	12/26/2019	
29408	FirstDraw	Tap	Rm 210 tap right outside rm 210 A	1	12/26/2019	
29409	FirstDraw	Tap	Student store	1	12/26/2019	
29410	FirstDraw	Tap	Rm 208C	2	12/26/2019	
29411	FirstDraw	Tap	Rm 267 left tap	5	12/26/2019	
29412	FirstDraw	Tap	Rm 267 middle tap	5	12/26/2019	

(continued)

Program ID	Sample Type	Description	Location	Lead Results (ppb)	Analysis Date	Comments
29413	FirstDraw	Tap	Rm 267 right tap	6	12/26/2019	
29414	FirstDraw	Tap	Rm 222	1	12/26/2019	
29415	FirstDraw	Bubbler	Bubblers between 225A and 225 staff restroom: low	<1	12/26/2019	
29416	FirstDraw	Bubbler	Bubblers between 225A and 225 staff restroom: high	<1	12/26/2019	
29418	FirstDraw	Tap	Rm 241 right most tap on window wall	5	12/26/2019	
29420	FirstDraw	Bubbler	Bubblers between rm 112 and 110: low	<1	12/26/2019	
29421	FirstDraw	Tap	Rm 253	2	12/26/2019	
29422	FirstDraw	Tap	Rm 110 back wall near exit	8	12/26/2019	
29423	FirstDraw	Tap	Rm 113	2	12/26/2019	
29424	FirstDraw	Bubbler	Bubblers between rm 125A and 125: low	<1	12/26/2019	
29425	FirstDraw	Bubbler	Bubblers between rm 125A and 125: high	<1	12/26/2019	
29426	FirstDraw	Tap	Rm 126	1	12/26/2019	
29429	FirstDraw	Tap	Rm 124 kitchen 1/left tap	1	12/26/2019	

(continued)

Program ID	Sample Type	Description	Location	Lead Results (ppb)	Analysis Date	Comments
29430	FirstDraw	Tap	Rm 141 back wall right tap	11	12/26/2019	
29431	FirstDraw	Tap	Rm 141 side wall middle tap	6	12/26/2019	
29432	FirstDraw	Tap	Rm 141 side wall left tap	4	12/26/2019	
29433	FirstDraw	Tap	Rm 141 front wall right tap	1	12/26/2019	
29434	FirstDraw	Tap	Rm 141 front wall middle tap	10	12/26/2019	
29435	FirstDraw	Tap	Rm 141 front wall left tap	18	12/26/2019	
29436	FirstDraw	Tap	Rm 124 kitchen 2/middle tap	1	12/26/2019	
29437	FirstDraw	Tap	Rm 124: kitchen 3/right tap	1	12/26/2019	
29438	FirstDraw	Tap	Rm 120	1	12/26/2019	Water used briefly
29439	FirstDraw	Tap	Custodial room: 101	1	12/26/2019	
29440	FirstDraw	Tap	Rm 122 kiln room	<1	12/24/2019	
29441	FirstDraw	Tap	Rm 122 right tap	1	12/26/2019	
29442	FirstDraw	Tap	Rm 122 middle tap	<1	12/26/2019	
29443	FirstDraw	Tap	Rm 122 left tap	1	12/26/2019	
29444	FirstDraw	Tap	Rm 241 side wall left tap	12	12/26/2019	

(continued)

Program ID	Sample Type	Description	Location	Lead Results (ppb)	Analysis Date	Comments
29445	FirstDraw	Tap	Rm 241 side wall middle tap	9	12/26/2019	
29446	FirstDraw	Tap	Rm 241 back wall with window: left tap	6	12/26/2019	
29447	FirstDraw	Tap	Rm 241 front wall right tap	11	12/26/2019	
29448	FirstDraw	Tap	Rm 241 front wall middle tap	10	12/26/2019	
29449	FirstDraw	Tap	Rm 241 front wall left tap	16	12/26/2019	