



Lead Sample Collection Information

DISCLAIMER: Results posted here only represent testing done by the Washington State Department of Health for the 2018-19 lead in school drinking water program. Schools have been provided these results, along with recommendations for remediation if applicable. Please contact your school to find out more about this and other testing they may have done, as well as plans for remediation.

Please note: Pot fillers are used infrequently and the result do not represent levels of lead to which students and staff would usually and regularly be exposed. The school has taken the fixture out of service and replaced with lead free certified fixtures all followed all recommendations for the remaining fixtures.

School District Name: Bremerton School District

School Name: Bremerton High School

School Code: 3109

Address: 1500 13th Street Bremerton WA 98337 Number of

Samples Collected: 47

Date Collected: 3/3/2018

Sample number	Sample ID	Sample Type	Fixture Description	Fixture Location	Lead Content (ppb)	Date of Analysis	Notes/Comments
Sample 1	2173	First Draw	Blank	Blank	<1	03/15/2018	Blank
Sample 2	2174	First Draw	Bubbler	Hall by Band Room	<1	03/15/2018	
Sample 3	2175	First Draw	Bottle Filler	Hall by Band Room	<1	03/15/2018	
Sample 4	2176	First Draw	Bubbler	Cafeteria/ Commons	<1	03/15/2018	
Sample 5	2177	First Draw	Bottle Filler	Cafeteria/ Commons	<1	03/15/2018	
Sample 6	2178	First Draw	Bubbler	Gym	<1	03/15/2018	Left Side when facing wall, low function
Sample 7	2179	First Draw	Bubbler	Gym	<1	03/15/2018	Right Side when facing wall
Sample 8	2180	First Draw	Tap	Kitchen	2	03/15/2018	Next to back room, used to fill carafes, etc.
Sample 9	2181	First Draw	Tap	Kitchen	71	03/15/2018	by walk-in refrigerator
Sample 10	2182	First Draw	Pot Filler	Kitchen	7080	08/08/2018	Very infrequent use, sample was very turbid and contained large amounts of sediment, rust, etc.
Sample 11	2183	First Draw	Bubbler	Across from Rm. 231	<1		
Sample 12	2184	First Draw	Bottle Filler	Across from Rm. 232	<1	03/15/2018	
Sample 13	2185	First Draw	Bubbler	Near Rm. 250	1	03/15/2018	
Sample 14	2186	First Draw	Tap	Rm. 250	1	03/15/2018	Irregular use, Tap on washing sink

Sample number	Sample ID	Sample Type	Fixture Description	Fixture Location	Lead Content (ppb)	Date of Analysis	Notes/Comments
Sample 15	2187	First Draw	Tap	Rm. 250	1	03/15/2018	Tap in corner
Sample 16	2188	First Draw	Bubbler	Across from Rm. 310	<1	03/15/2018	
Sample 17	2189	First Draw	Bottle Filler	Across from Rm. 311	<1	03/15/2018	
Sample 18	2190	First Draw	Bubbler	Across from Rm. 326	1	03/15/2018	
Sample 19	2191	First Draw	Bubbler	Next to Rm. 111	<1	03/15/2018	
Sample 20	2192	First Draw	Tap	Rm. 124	3	03/15/2018	Special Ed. Room
Sample 21	2193	First Draw	Tap	Rm. 126	9	03/15/2018	Special Ed. Room
Sample 22	2194	First Draw	Bubbler	Hall by Rm. 126	<1	03/15/2018	
Sample 23	2195	First Draw	Tap	ROTC	4	03/15/2018	Left-hand Tap
Sample 24	2196	First Draw	Tap	ROTC	4	03/15/2018	Right-hand Tap, Bubbler did not function
Sample 25	2197	First Draw	Bubbler	Rm. 110	1	03/15/2018	Home Ec. Room, Taps Clockwise Starting Next to Bubbler
Sample 26	2198	First Draw	Tap	Rm. 110	1	03/15/2018	Station 1
Sample 27	2199	First Draw	Tap	Rm. 110	1	03/15/2018	Station 2
Sample 28	2200	First Draw	Tap	Rm. 110	1	03/15/2018	Station 3
Sample 29	2201	First Draw	Tap	Rm. 110	1	03/15/2018	Station 4

Sample number	Sample ID	Sample Type	Fixture Description	Fixture Location	Lead Content (ppb)	Date of Analysis	Notes/Comments
Sample 30	2202	First Draw	Tap	Rm. 110	2	03/15/2018	Station 5
Sample 31	2203	First Draw	Tap	Rm. 110	1	03/15/2018	Station 6
Sample 32	2204	First Draw	Tap	Rm. 110	1	03/15/2018	Station 7
Sample 33	2205	First Draw	Bubbler	Across from Rm. 407	<1	03/15/2018	400 Wing Hall
Sample 34	2206	First Draw	Bottle Filler	Across from Rm. 408	<1	03/15/2018	400 Wing Hall
Sample 35	2207	First Draw	Bubbler	Women's Locker Room	1	03/15/2018	
Sample 36	2208	First Draw	Bubbler	Men's Locker Room	<1	03/15/2018	
Sample 37	2209	First Draw	Bubbler	Weight Room	<1	03/15/2018	
Sample 38	2210	First Draw	Bubbler	Band Room	9	03/15/2018	
Sample 39	2211	First Draw	Bubbler	Fitness Center	1	03/15/2018	Upper Left, Lower Right did not function
Sample 40	2212	First Draw	Bubbler	Stadium	2	03/15/2018	Next to women's Restroom, irregular use
Sample 41	2213	First Draw	Tap	Concession Building	6	08/08/2018	Seasonal Use, Had not been used for long period of time
Sample 42	2214	First Draw	Water Cooler	Portable 601	<1	03/15/2018	
Sample 43	2215	First Draw	Water Cooler	Portable 603	<1	03/15/2018	

Sample number	Sample ID	Sample Type	Fixture Description	Fixture Location	Lead Content (ppb)	Date of Analysis	Notes/Comments
Sample 44	2216	First Draw	Bubbler	Restroom Portable	<1	03/15/2018	between restrooms
Sample 45	2217	First Draw	Tap	Nurse	2	03/15/2018	
Sample 46	2218	First Draw	Tap	Rm. 206	1	03/15/2018	
Sample 47	2219	First Draw	Water Cooler	2nd Floor Special Ed.	<1	03/15/2018	