



Lead Sample Collection Information

DISCLAIMER: Results posted here only represent testing done by the Washington State Department of Health for the 2018-19 lead in school drinking water program. Schools have been provided these results, along with recommendations for remediation if applicable. Please contact your school to find out more about this and other testing they may have done, as well as plans for remediation.

Please Note: The school has replaced all fixtures that were tested above 9ppb with lead free certified fixtures and has followed recommendations to reduce children's overall exposure to lead.

School District Name: Snoqualmie Valley

School Name: Cascade View

School Code: 5015

Address: 34816 SE Ridge St Snoqualmie WA 98065

Number of Samples Collected: 71

Date Collected: 4/20/2018

Sample number	Sample ID	Sample Type	Fixture Description	Fixture Location	Lead Content (ppb)	Date of Analysis	Notes/Comments
Sample 1	7451	First Draw	Pot Filler	Kitchen	10	08/09/2018	Smaller pot on left side
Sample 2	7456	First Draw	Pot Filler	Kitchen	267	8/20/2018	Larger pot on right side
Sample 3	7457	First Draw	Tap	Kitchen	<1	8/20/2018	
Sample 4	7458	First Draw	Sprayer	Kitchen	1	08/09/2018	
Sample 5	7459	First Draw	Tap	Nurse's Room	1	08/09/2018	
Sample 6	7460	First Draw	Tap	Staff Room	6	08/09/2018	
Sample 7	7461	First Draw	Bubbler	Staff Workroom	8	8/20/2018	
Sample 8	7462	First Draw	Tap	Staff Workroom	9	08/09/2018	
Sample 9	7463	First Draw	Drinking Fountain, Left	Near Room 12	<1	08/09/2018	
Sample 10	7464	First Draw	Drinking Fountain, Right	Near Room 12	<1	08/09/2018	
Sample 11	7465	First Draw	Bubbler	Room 12	<1	08/09/2018	
Sample 12	7466	First Draw	Tap	Room 12	<1	08/09/2018	calcification on aerator
Sample 13	7467	First Draw	Bubbler	Room 14	3	8/20/2018	calcification
Sample 14	7468	First Draw	Tap	Room 14	4	8/20/2018	
Sample 15	7469	First Draw	Bubbler	Near Room 14	5	08/09/2018	calcification
Sample 16	7470	First Draw	Tap	Near Room 14	<1	08/09/2018	
Sample 17	7471	First Draw	Bubbler	Room 16	1	08/09/2018	calcification
Sample 18	7472	First Draw	Tap	Room 16	4	08/09/2018	

Sample number	Sample ID	Sample Type	Fixture Description	Fixture Location	Lead Content (ppb)	Date of Analysis	Notes/Comments
Sample 19	7473	First Draw	Bubbler	Room 18	4	08/09/2018	calcification
Sample 20	7474	First Draw	Tap	Room 18	4	08/09/2018	
Sample 21	7475	First Draw	Bubbler	Room 19	1	08/09/2018	
Sample 22	7476	First Draw	Tap	Room 19	1	08/09/2018	
Sample 23	7477	First Draw	Bubbler	Room 17	5	8/20/2018	calcification
Sample 24	7478	First Draw	Tap	Room 17	7	8/20/2018	
Sample 25	7479	First Draw	Bubbler	Room 15	1	08/09/2018	
Sample 26	7480	First Draw	Tap	Room 15	1	08/09/2018	
Sample 27	7481	First Draw	Bubbler	Room 13	2	08/09/2018	
Sample 28	7482	First Draw	Tap	Room 13	1	08/09/2018	
Sample 29	7483	First Draw	Bubbler	Near Room 21	<1	08/09/2018	
Sample 30	7484	First Draw	Tap	Near Room 21	<1	08/09/2018	
Sample 31	7485	First Draw	Bubbler	Room 20	2	08/09/2018	
Sample 32	7486	First Draw	Tap	Room 20	2	08/09/2018	
Sample 33	7487	First Draw	Bubbler	Near Room 20	2	08/09/2018	
Sample 34	7488	First Draw	Tap	Near Room 20	6	08/09/2018	
Sample 35	7489	First Draw	Bubbler	Room 22	2	08/09/2018	
Sample 36	7490	First Draw	Tap	Room 22	<1	08/09/2018	
Sample 37	7491	First Draw	Tap	Room 24	4	8/20/2018	
Sample 38	7492	First Draw	Bubbler	Room 25	<1	8/20/2018	
Sample 39	7493	First Draw	Tap	Room 25	3	8/20/2018	
Sample 40	7494	First Draw	Bubbler	Room 26	<1	08/09/2018	

Sample number	Sample ID	Sample Type	Fixture Description	Fixture Location	Lead Content (ppb)	Date of Analysis	Notes/Comments
Sample 41	7495	First Draw	Tap	Room 26	2	08/09/2018	
Sample 42	7496	First Draw	Bubbler	Room 23	1	08/09/2018	
Sample 43	7497	First Draw	Tap	Room 23	1	08/09/2018	
Sample 44	7498	First Draw	Bubbler	Room 21	1	08/09/2018	
Sample 45	7499	First Draw	Tap	Room 21	1	08/09/2018	
Sample 46	7500	First Draw	Bubbler	Room 4	<1	08/09/2018	
Sample 47	7501	First Draw	Tap	Room 4	<1	08/09/2018	
Sample 48	7502	First Draw	Bubbler	Room 6	1	08/09/2018	
Sample 49	7503	First Draw	Tap	Room 6	1	08/09/2018	
Sample 50	7504	First Draw	Bubbler	Near Room 6	5	08/09/2018	
Sample 51	7505	First Draw	Tap	Near Room 6	2	08/09/2018	
Sample 52	7506	First Draw	Bubbler	Room 8	1	08/09/2018	
Sample 53	7507	First Draw	Tap	Room 8	1	08/09/2018	
Sample 54	7508	First Draw	Bubbler	Room 10	1	08/09/2018	calcification
Sample 55	7509	First Draw	Tap	Room 10	4	8/20/2018	
Sample 56	7510	First Draw	Bubbler	Room 11	1	8/9/2018	
Sample 57	7511	First Draw	Tap	Room 11	1	08/09/2018	
Sample 58	7512	First Draw	Bubbler	Room 9	1	08/09/2018	
Sample 59	7513	First Draw	Tap	Room 9	1	08/09/2018	
Sample 60	7514	First Draw	Bubbler	Room 7	1	08/09/2018	
Sample 61	7515	First Draw	Tap	Room 7	1	08/09/2018	
Sample 62	7516	First Draw	Bubbler	Room 5	1	08/09/2018	

Sample number	Sample ID	Sample Type	Fixture Description	Fixture Location	Lead Content (ppb)	Date of Analysis	Notes/Comments
Sample 63	7517	First Draw	Tap	Room 5	1	08/09/2018	
Sample 64	7518	First Draw	Drinking Fountain, Left	Near Room 5	<1	08/09/2018	leaks
Sample 65	7519	First Draw	Drinking Fountain, Right	Near Room 5	<1	08/09/2018	
Sample 66	7520	First Draw	Drinking Fountain	Outside Cafeteria	<1	08/09/2018	
Sample 67	7521	First Draw	Bottle Filler	Outside Cafeteria	<1	08/09/2018	
Sample 68	7522	First Draw	Watercooler	P-31	<1	08/09/2018	
Sample 69	7523	First Draw	Watercooler	P-30	<1	08/09/2018	
Sample 70	7524	First Draw	Watercooler	P-32	<1		
Sample 71	7525	First Draw	Watercooler	P-33	<1	8/10/2018	
Sample 72	7526	First Draw	Blank	P-33	<1	8/10/2018	05883