



Office of Environmental Public Health Sciences
Washington State Department of Health
243 Israel Road Southeast, Tumwater Washington 98501

Lead Sample Collection Information

DISCLAIMER: Results posted here only represent testing done by the Washington State Department of Health for the 2018-19 lead in school drinking water program. Schools have been provided these results, along with recommendations for remediation if applicable. Please contact your school to find out more about this and other testing they may have done, as well as plans for remediation.

Please Note: The school is following all recommended remediation to help reduce children's exposure to lead in drinking water.

School District: Kent

School Name: Kent Elementary

School Code: 4520

School Address: 24700 64th Ave South, Kent Washington 98032

Number of Samples Collected: 68

Date Collected: 03/28/2019

Program ID	Sample Type	Description	Location	Lead Results (ppb)	Analysis Date	Comments
21999	other	other		<1	04/15/2019	6:56 AM, 02560
22000	FirstDraw	Bubbler	Stage Behind Cafeteria	<1	04/15/2019	
22001	FirstDraw	Tap	Stage Behind Cafeteria	1	04/15/2019	
22002	FirstDraw	Bubbler	Commons Area Near Cafeteria	<1	04/15/2019	Left Bubbler, West Wall
22003	FirstDraw	Bubbler	Commons Area Near Cafeteria	<1	04/15/2019	Right Bubbler, West Wall
22004	FirstDraw	Bubbler	Commons Area, East Wall	<1	04/15/2019	Used this morning
22005	FirstDraw	Tap	Commons Area, East Wall	<1	04/15/2019	Used this morning
22006	FirstDraw	Bubbler	Music Room Near Commons Area	<1	04/15/2019	
22007	FirstDraw	Tap	Music Room Near Commons Area	<1	04/15/2019	
22008	FirstDraw	Tap	Main Office	<1	04/15/2019	
22009	FirstDraw	Tap	Room 412, Health Room	<1	04/15/2019	
22010	FirstDraw	Tap	Staff Lounge	<1	04/15/2019	Minerals built up around aerator
22011	FirstDraw	Tap	Workroom	<1	04/15/2019	
22012	FirstDraw	Tap	Library Sink	1	04/15/2019	
22013	FirstDraw	Bubbler	Room 103	<1	04/15/2019	
22014	FirstDraw	Tap	Room 103	1	04/15/2019	No Aerator

(continued)

Program ID	Sample Type	Description	Location	Lead Results (ppb)	Analysis Date	Comments
22015	FirstDraw	Bubbler	Room 105	<1	04/15/2019	Some mineral deposits near mouth of bubbler
22016	FirstDraw	Tap	Room 105	<1	04/15/2019	
22017	FirstDraw	Bubbler	Room 107	<1	04/15/2019	Some mineral deposits on bubbler
22018	FirstDraw	Tap	Room 107	<1	04/15/2019	
22019	FirstDraw	Bubbler	Room 109	<1	04/15/2019	Base leaks a little
22020	FirstDraw	Tap	Room 109	<1	04/15/2019	
22021	FirstDraw	Bubbler	Room 110	<1	04/15/2019	Some mineral deposits on bubbler
22022	FirstDraw	Tap	Room 110	<1	04/15/2019	
22023	FirstDraw	Tap	Room 110	4	04/15/2019	West Inner Wall
22024	FirstDraw	Bubbler	Room 108	<1	04/15/2019	
22025	FirstDraw	Tap	Room 108	<1	04/15/2019	North Wall
22026	FirstDraw	Tap	Room 108	1	04/15/2019	West Inner Wall
22027	FirstDraw	Bubbler	Room 106	<1	04/15/2019	Some mineral deposits near mouth of bubbler
22028	FirstDraw	Tap	Room 106	1	04/15/2019	
22029	FirstDraw	Bubbler	Room 104	<1	04/15/2019	
22030	FirstDraw	Tap	Room 104	4	04/30/2019	
22031	FirstDraw	Bubbler	Room 102	<1	04/15/2019	
22032	FirstDraw	Tap	Room 102	<1	04/15/2019	No Aerator, Hot Water Tap Used
22033	FirstDraw	Bubbler	Room 101, Reading Hull	1	04/15/2019	

(continued)

Program ID	Sample Type	Description	Location	Lead Results (ppb)	Analysis Date	Comments
22034	FirstDraw	Tap	Room 101, Reading Hull	<1	04/15/2019	
22035	FirstDraw	Bubbler	Room 207	<1	04/15/2019	Some mineral deposits near mouth
22036	FirstDraw	Tap	Room 207	<1	04/15/2019	
22037	FirstDraw	Bubbler	Room 209	<1	04/15/2019	
22038	FirstDraw	Tap	Room 209	<1	04/15/2019	Tap used this morning
22039	FirstDraw	Bubbler	Room 211	<1	04/15/2019	
22040	FirstDraw	Tap	Room 211	<1	04/15/2019	
22041	FirstDraw	Bubbler	Room 213	<1	04/15/2019	
22042	FirstDraw	Tap	Room 213	<1	04/15/2019	
22043	FirstDraw	Bubbler	Room 212	<1	04/15/2019	Bubbler Dripping
22044	FirstDraw	Tap	Room 212	<1	04/15/2019	
22045	FirstDraw	Bubbler	Room 210	<1	04/15/2019	Some erosion and deposits on mouth
22046	FirstDraw	Tap	Room 210	<1	04/15/2019	
22047	FirstDraw	Bubbler	Room 208	<1	04/15/2019	
22048	FirstDraw	Tap	Room 208	<1	04/15/2019	
22049	FirstDraw	Bubbler	Room 206	<1	04/15/2019	Some mineral deposits near mouth
22050	FirstDraw	Tap	Room 206	<1	04/15/2019	
22051	FirstDraw	Bubbler	Room 301	<1	04/15/2019	Some mineral deposits
22052	FirstDraw	Tap	Room 301	<1	04/15/2019	
22053	FirstDraw	Bubbler	Room 307	<1	04/15/2019	
22054	FirstDraw	Tap	Room 307	<1	04/15/2019	
22055	FirstDraw	Bubbler	Room 309	<1	04/15/2019	
22056	FirstDraw	Tap	Room 309	<1	04/16/2019	

(continued)

Program ID	Sample Type	Description	Location	Lead Results (ppb)	Analysis Date	Comments
22057	FirstDraw	Bubbler	Outside Near 300 Hall	<1	04/16/2019	
22058	FirstDraw	Bubbler	Room 308	<1	04/16/2019	Mineral deposits on mouth of bubbler
22059	FirstDraw	Tap	Room 308	1	04/16/2019	
22060	FirstDraw	Bubbler	Room 306	<1	04/16/2019	
22061	FirstDraw	Tap	Room 306	<1	04/16/2019	
22062	Flush	Bubbler	Room 304	<1	04/16/2019	
22063	FirstDraw	Tap	Room 304	<1	04/16/2019	No Aerator
22064	FirstDraw	WaterCooler	Portable 7	<1	04/16/2019	
22065	FirstDraw	WaterCooler	Portable 5	<1	04/16/2019	
22066	FirstDraw	WaterCooler	Portable 6	<1	04/16/2019	