



Office of Environmental Public Health Sciences  
Washington State Department of Health  
243 Israel Road Southeast, Tumwater Washington 98501

## Lead Sample Collection Information

**DISCLAIMER:** Results posted here only represent testing done by the Washington State Department of Health for the 2018-19 lead in school drinking water program. Schools have been provided these results, along with recommendations for remediation if applicable. Please contact your school to find out more about this and other testing they may have done, as well as plans for remediation.

Please note: The school district is participating in follow up testing and is following recommendations to reduce children's overall exposure to lead.

**School District:** Kelso

**School Name:** Catlin Elementary School

**School Code:** 2691

**School Address:** 404 Long Ave, Kelso Washington 98626

**Number of Samples Collected:** 53

**Date Collected:** 01/15/2019

Program ID	Sample Type	Description	Location	Lead Results (ppb)	Analysis Date	Comments
	FirstDraw	Bubbler	Next to Rm 10	TB	NA	
18802	other			<1	01/23/2019	
18803	FirstDraw	Tap	Kitchen	2	01/23/2019	Triple sink left tap
18804	FirstDraw	Tap	Kitchen	4	01/23/2019	Triple sink right tap
18805	FirstDraw	Bubbler	Next to Rm 24	2	01/23/2019	Left
18806	FirstDraw	Bubbler	Next to Rm 24	2	01/23/2019	Right
18807	FirstDraw	Bubbler	Rm 23	4	01/23/2019	
18808	FirstDraw	Tap	Rm 23	4	01/23/2019	
18809	FirstDraw	Tap	Rm 22	2	01/23/2019	
18810	FirstDraw	Bubbler	Rm 19	2	01/23/2019	
18811	FirstDraw	Tap	Rm 19	7	01/23/2019	
18812	FirstDraw	Bubbler	Rm 21	3	01/23/2019	
18813	FirstDraw	Tap	Rm 21	<1	01/23/2019	
18814	FirstDraw	Bubbler	Next to Rm 20	1	01/23/2019	Left only, right side no function
18815	FirstDraw	Bubbler	Rm 18	1	01/23/2019	
18816	FirstDraw	Tap	Rm 18	8	01/23/2019	
18817	FirstDraw	Bubbler	Rm 17	2	01/23/2019	
18818	FirstDraw	Tap	Rm 17	6	01/23/2019	Right side sink
18819	FirstDraw	Tap	Rm 17	5	01/23/2019	Left side sink
18820	FirstDraw	Bubbler	Rm 16	3	01/23/2019	
18821	FirstDraw	Tap	Rm 16	3	01/23/2019	
18822	FirstDraw	Bubbler	Next to Rm 16	1	01/23/2019	Right side only
18823	FirstDraw	Bubbler	Rm 15	3	01/23/2019	
18824	FirstDraw	Tap	Rm 15	2	01/23/2019	
18825	FirstDraw	Bubbler	Rm 14	3	01/23/2019	
18826	FirstDraw	Tap	Rm 14	4	01/23/2019	Slow drip
18827	FirstDraw	Bubbler	Nurse	8	01/23/2019	
18828	FirstDraw	Tap	Nurse	16	01/23/2019	

(continued)

Program ID	Sample Type	Description	Location	Lead Results (ppb)	Analysis Date	Comments
18829	FirstDraw	Tap	Rm 13	9	02/27/2019	Bubbler function too low to test
18830	FirstDraw	Bubbler	Rm 12	1	01/23/2019	
18831	FirstDraw	Tap	Rm 12	3	01/23/2019	
18832	FirstDraw	Bubbler	Rm 11	12	01/23/2019	
18833	FirstDraw	Tap	Rm 11	2	01/23/2019	
18834	FirstDraw	Bubbler	Rm 10	2	01/23/2019	
18835	FirstDraw	Tap	Rm 10	1	01/23/2019	
18836	FirstDraw	Bubbler	Rm 9	7	01/23/2019	
18837	FirstDraw	Tap	Rm 9	4	01/23/2019	
18839	FirstDraw	Bubbler	Rm 8	11	01/23/2019	
18840	FirstDraw	Tap	Rm 8	16	02/27/2019	
18841	FirstDraw	Bubbler	Rm 7	4	01/23/2019	
18842	FirstDraw	Tap	Rm 7	2	01/23/2019	
18843	FirstDraw	Bubbler	Across from Rm 6-A	10	01/23/2019	
18844	FirstDraw	Bubbler	Rm 6	1	01/23/2019	
18845	FirstDraw	Tap	Rm 6	4	01/23/2019	
18846	FirstDraw	Bubbler	Rm 5	2	01/23/2019	Low function
18847	FirstDraw	Tap	Rm 5	3	01/23/2019	Low pressure
18848	FirstDraw	Bubbler	Rm 4	<1	01/23/2019	Low function
18849	FirstDraw	Tap	Rm 4	7	01/23/2019	
18850	FirstDraw	Bubbler	Rm 3	<1	01/23/2019	
18851	FirstDraw	Tap	Rm 3	21	01/23/2019	
18852	FirstDraw	Bubbler	Rm 2	1	01/23/2019	
18853	FirstDraw	Tap	Rm 2	15	01/23/2019	
18854	FirstDraw	Bubbler	Rm 1	1	01/23/2019	
18855	FirstDraw	Tap	Rm 1	9	01/23/2019	