



Lead Sample Collection Information

School District Name: Washtucna School District
School Name: Washtucna Elementary/High School
School Code: 3075
Address: 730 E. Booth Ave Washtucna, WA 99371
Number of Samples Collected: 27
Date Collected: 2/22/2018

Sample number	Sample ID	Sample Type	Fixture Description	Fixture Location	Lead Content (ppb)	Date of Analysis	Notes/Comments
Sample No	Program ID (See label)	Sample Type	Fixture Description	Fixture Location	Lead results (ppb)	Date of Analysis	Notes/comments
Sample 1	644	First Draw	Sink	Room 6	7	2/27/2018	
Sample 2	645	First Draw	Bubbler	Near Room D	7	2/27/2018	Low Pressure
Sample 3	646	First Draw	Sink	Room 4	2	2/27/2018	
Sample 4	647	First Draw	Sink	Room 2	2	2/27/2018	Discolored, Left side of the room, Left Sink
Sample 5	648	First Draw	Sink	Room 2	2	2/27/2018	Left Side Room, Right Sink
Sample 6	649	First Draw	Sink	Room 2	57	2/27/2018	Front Room, Left Sink
Sample 7	650	First Draw	Sink	Room 2	2	2/27/2018	Front Room, Right Sink
Sample 8	651	First Draw	Sink	Kitchen	1	2/27/2018	Left Sink
Sample 9	652	First Draw	Sink	Kitchen	107	2/27/2018	Front Sink
Sample 10	653	First Draw	Sink	Kitchen	<1	2/27/2018	Right Sink
Sample 11	654	First Draw	Bubbler	Outside of the Gym	<1	2/27/2018	
Sample 12	655	First Draw	Bubbler	Outside of the Gym	4	2/27/2018	Water Bottle Filler
Sample 13	656	First Draw	Sink	Room 13	5	2/27/2018	Low Pressure

Sample number	Sample ID	Sample Type	Fixture Description	Fixture Location	Lead Content (ppb)	Date of Analysis	Notes/Comments
Sample 14	657	First Draw	Bubbler	Hallway next to the Janitor's Closet, Near Room 13	5	2/27/2018	
Sample 15	658	First Draw	Sink	Room 15	2	2/27/2018	Dripping
Sample 16	659	First Draw	Sink	Room 17	3	2/27/2018	
Sample 17	660	First Draw	Bubbler	Room 17	1	2/27/2018	
Sample 18	661	First Draw	Sink	Room 18	17	2/27/2018	
Sample 19	662	First Draw	Bubbler	Room 18	2	2/27/2018	
Sample 20	663	First Draw	Sink	Room 19	6	2/27/2018	
Sample 21	664	First Draw	Bubbler	Room 19	3	2/27/2018	
Sample 22	665	First Draw	Sink	Room 20	<1	2/27/2018	
Sample 23	666	First Draw	Bubbler	Room 20	28	2/27/2018	
Sample 24	667	First Draw	Bubbler	Right Entry Way	24	2/27/2018	
Sample 25	668	First Draw	Sink	Main Room, Front Right Sink	Left Sink, Does n't work	2/27/2018	
Sample 26	669	First Draw	Sink	Shop/Heavy	Right Sink	2/27/2018	

Sample number	Sample ID	Sample Type	Fixture Description	Fixture Location	Lead Content (ppb)	Date of Analysis	Notes/Comments
				Machine Room			
Sample 27	670	First Draw	Sink	Shop/Heavy Machine Room	Left Sink	2/27/2018	