



Lead Sample Collection Information

DISCLAIMER: Results posted here only represent testing done by the Washington State Department of Health for the 2018-19 lead in school drinking water program. Schools have been provided these results, along with recommendations for remediation if applicable. Please contact your school to find out more about this and other testing they may have done, as well as plans for remediation.

School District Name: Kettle Falls School District

School Name: Kettle Falls Middle School

School Code: 3198

Address: 105 W. 11th Ave Kettle Falls WA 99141

Number of Samples Collected: 25

Date Collected: 3/21/2018

Sample number	Sample ID	Sample Type	Fixture Description	Fixture Location	Lead Content (ppb)	Date of Analysis	Notes/Comments
Sample 1	3701	First Draw	Tap	Kitchen	10	5/19/2018	Left Tap
Sample 2	3702	First Draw	Tap	Kitchen	10	5/19/2018	Right Tap, Drips
Sample 3	3703	First Draw	Tap	Room 10	11	5/19/2018	
Sample 4	3704	First Draw	Bubbler	Outside of Gym	<1	5/19/2018	
Sample 5	3705	First Draw	Bottle Filler	Outside of Gym	<1	5/19/2018	
Sample 6	3706	First Draw	Tap	Concession Stand Room	4	5/19/2018	
Sample 7	3707	First Draw	Bubbler	Outside of Room 14	<1	5/19/2018	
Sample 8	3708	First Draw	Bottle Filler	Outside of Room 14	<1	5/19/2018	
Sample 9	3709	First Draw	Tap	Room 14	14	5/19/2018	Left Tap
Sample 10	3710	First Draw	Tap	Room 14	6	5/19/2018	Right Tap
Sample 11	3711	First Draw	Tap	Room 15	5	5/19/2018	Closest to the Door. Lone Sink on that wall
Sample 12	3712	First Draw	Tap	Room 15	11	5/19/2018	Left most Sink of 3 on the back wall
Sample 13	3713	First Draw	Tap	Room 15	27	5/19/2018	Middle Sink of 3 on the back wall
Sample 14	3714	First Draw	Tap	Room 15	22	5/19/2018	Closest to the windows. Lone Sink on that wall
Sample 15	3715	First Draw	Tap	Room 20	6	5/19/2018	
Sample 16	3716	First Draw	Bubbler	Room 20	TB	5/19/2018	Greenish/Blue particles in the water
Sample 17	3717	First Draw	Tap	Room 22	8	5/19/2018	
Sample 18	3718	First Draw	Bubbler	Back Hall between	<1	5/19/2018	

Sample number	Sample ID	Sample Type	Fixture Description	Fixture Location	Lead Content (ppb)	Date of Analysis	Notes/Comments
				Room 22-23			
Sample 19	3719	First Draw	Bottle Filler	Back Hall between Room 22-23	<1	5/19/2018	
Sample 20	3720	First Draw	Tap	Back Hall between Room 22-23	4	5/19/2018	
Sample 21	3721	First Draw	Tap	Room 23	4	5/19/2018	
Sample 22	3722	First Draw	Bubbler	Room 23	6	5/19/2018	
Sample 23	3723	First Draw	Tap	Room 24	4	5/19/2018	
Sample 24	3724	First Draw	Tap	Back Hall between Room 24-25	4	5/19/2018	
Sample 25	3725	First Draw	Tap	Room 25	TB	5/19/2018	Left Tap, Discolored
Sample 26	3726	First Draw	Tap	Room 25	14	5/19/2018	Right Tap