



Office of Environmental Public Health Sciences
Washington State Department of Health
243 Israel Road Southeast, Tumwater Washington 98501

Lead Sample Collection Information

DISCLAIMER: Results posted here only represent testing done by the Washington State Department of Health for the 2018-19 lead in school drinking water program. Schools have been provided these results, along with recommendations for remediation if applicable. Please contact your school to find out more about this and other testing they may have done, as well as plans for remediation.

Please Note: The school is following all recommended remediation to help reduce children's exposure to lead in drinking water.

School District: Marysville

School Name: Marysville ECEAP

School Code: 1895

School Address: 4317 76th St Northeast, Marysville Washington 98270

Number of Samples Collected: 37

Date Collected: 05/31/2019

Program ID	Sample Type	Description	Location	Lead Results (ppb)	Analysis Date	Comments
24836	other	other		<1	06/18/2019	06720, 6:06 AM
24837	FirstDraw	Tap	Kitchen, Food Prep Area	1	06/18/2019	
24838	FirstDraw	Bubbler	Cafeteria	<1	06/18/2019	
24839	FirstDraw	Tap	Portable G-1	<1	06/18/2019	
24840	FirstDraw	WaterCooler	Portable G-1	<1	06/18/2019	
24841	FirstDraw	Tap	Portable G-2	1	06/18/2019	Adjacent to G-1
24842	FirstDraw	Tap	Room 430	1	06/18/2019	
24843	FirstDraw	WaterCooler	Room 430	<1	06/18/2019	
24844	FirstDraw	Tap	Room 431	<1	06/18/2019	
24845	FirstDraw	WaterCooler	Room 431	<1	06/18/2019	May or may not be used (left unplugged)
24846	FirstDraw	Tap	Room 432	<1	06/18/2019	
24847	FirstDraw	WaterCooler	Room 432	<1	06/18/2019	
24848	FirstDraw	Tap	Room 433	<1	06/18/2019	
24849	FirstDraw	WaterCooler	Room 433	<1	06/18/2019	Behind Desk
24850	FirstDraw	WaterCooler	Room 534	<1	06/18/2019	
24851	FirstDraw	Tap	Room 534	<1	06/18/2019	East Wall going clockwise starting at sink on far left
24852	FirstDraw	Tap	Room 534	2	06/18/2019	2nd Sink moving clockwise
24853	FirstDraw	Tap	Room 534	16	06/18/2019	3rd sink moving clockwise
24854	FirstDraw	Tap	Room 534	28	06/18/2019	4th Sink moving clockwise, on south Wall (far left)

(continued)

Program ID	Sample Type	Description	Location	Lead Results (ppb)	Analysis Date	Comments
24855	FirstDraw	Tap	Room 534	15	06/18/2019	6th Sink clock wise (suspect 5th Sink not in use)
24856	FirstDraw	Tap	Room 536	2	06/18/2019	
24857	FirstDraw	WaterCooler	Room 536	<1	06/18/2019	
24858	FirstDraw	WaterCooler	Room 640	<1	06/18/2019	
24859	FirstDraw	Tap	Room 640	1	06/18/2019	First sink on East Wall (moving in a clockwise direction from this tap)
24860	FirstDraw	Tap	Room 640	2	06/18/2019	2nd Sink moving clockwise
24861	FirstDraw	Tap	Room 640	TB	NA	3rd Sink moving clockwise
24862	FirstDraw	Tap	Room 640	3	06/18/2019	4th Sink moving clockwise
24863	FirstDraw	WaterCooler	Room 642	<1	06/18/2019	
24864	FirstDraw	Tap	Room 642, Office	3	06/18/2019	
24865	FirstDraw	Tap	Room 642, Classroom Side	2	06/18/2019	Other side of office
24866	FirstDraw	Tap	Room 644	4	06/18/2019	
24867	FirstDraw	Bubbler	Main Office	1	06/18/2019	Near Front Desk
24868	FirstDraw	Tap	Nurses Room , Room 102	5	06/18/2019	
24869	FirstDraw	WaterCooler	Room 219	<1	06/18/2019	
24870	FirstDraw	Tap	Room 219	<1	06/18/2019	
24871	FirstDraw	WaterCooler	Room 217	<1	06/18/2019	
24872	FirstDraw	Tap	Room 217	<1	06/18/2019	