



**Office of Environmental Public Health Sciences
Washington State Department of Health
243 Israel Road SE, Tumwater WA 98501**

Lead Sample Collection Information

DISCLAIMER: Results posted here only represent testing done by the Washington State Department of Health for the 2018-19 lead in school drinking water program. Schools have been provided these results, along with recommendations for remediation if applicable. Please contact your school to find out more about this and other testing they may have done, as well as plans for remediation.

Please note: The school has replaced all fixtures that have lead levels above 19ppb. The school has also implemented a flushing program means of reducing lead in drinking water fixtures.

School Name: Terminal Park Elementary

School Code: 2659

School District Name: Auburn

Address: 1101 D St SE, Auburn WA 98002

County: King

Number of Samples Collected: 42

Date Collected: 06/13/2018

Sample number	Sample ID	Sample Type	Fixture Description	Fixture Location	Lead Content (ppb)	Date of Analysis	Notes/Comments
1.	10902	First Draw	Bubbler	Gym	<1	08/10/2018	6:10 AM
2.	10903	First Draw	Tap	Kitchen Sink for Food Prep	3	08/10/2018	
3.	10904	First Draw	Pot Filler	Kitchen	26	08/10/2018	
4.	10905	First Draw	Bubble	Left of 212 (Girls Bathroom)	1	08/10/2018	
5.	10906	First Draw	Bubbler	Across Hall from 212	5	08/10/2018	
6.	10907	First Draw	Bubbler	Room 205	<1	08/10/2018	Bubbler and Tap Sink
7.	10908	First Draw	Tap	Room 205	3	08/10/2018	Bubbler and Tap Sink
8.	10909	First Draw	Bubbler	Room 205	12	08/10/2018	
9.	10910	First Draw	Bubbler	Drinking fountain across from Room 204	9	08/10/2018	
10.	10911	First Draw	Bubbler	Right of 202 (girls bathroom)	1	08/10/2018	
11.	10912	First Draw	Bubbler	Room 203	2	08/10/2018	
12.	10913	First Draw	Tap	Room 203	2	08/10/2018	
13.	10914	First Draw	Bubbler	Room 201	8	08/10/2018	
14.	10915	First Draw	Tap	Room 201	9	08/10/2018	
15.	10916	First Draw	Bubbler	Room 200	2	08/10/2018	
16.	10917	First Draw	Tap	Room 200	32	08/15/2018	No aerator

Sample number	Sample ID	Sample Type	Fixture Description	Fixture Location	Lead Content (ppb)	Date of Analysis	Notes/Comments
17.	10918	First Draw	Bubbler	Next to 100 (Office)	1	08/10/2018	
18.	10919	First Draw	Tap	Nurses Office	4	08/10/2018	
19.	10920	First Draw	Tap	Workroom	1	08/10/2018	
20.	10949	First Draw	Tap	Staff Lounge	<1	08/10/2018	
21.	10950	First Draw	Bubbler	Room 300	2	08/10/2018	
22.	10951	First Draw	Tap	Room 300	1	08/10/2018	
23.	10952	First Draw	Bubbler	Room 301	1	08/10/2018	
24.	10953	First Draw	Tap	Room 301	<1	08/10/2018	
25.	10954	First Draw	Bubbler	Room 302	1	08/10/2018	
26.	10955	First Draw	Tap	Room 302	<1	08/10/2018	
27.	10956	First Draw	Bubbler	Room 303	1	08/10/2018	
28.	10957	First Draw	Tap	Room 303	<1	08/10/2018	No aerator
29.	10958	First Draw	Bubbler	Room 304	1	08/10/2018	
30.	10959	First Draw	Tap	Room 304	1	08/10/2018	No aerator
31.	10960	First Draw	Bubbler	Room 305	2	08/10/2018	
32.	10961	First Draw	Tap	Room 305	<1	08/10/2018	No aerator
33.	10962	First Draw	Bubbler	Room 114	5	08/10/2018	
34.	10963	First Draw	Tap	Room 114	3	08/10/2018	
35.	10964	First Draw	Bubbler	Room 116	1	08/10/2018	

Sample number	Sample ID	Sample Type	Fixture Description	Fixture Location	Lead Content (ppb)	Date of Analysis	Notes/Comments
36.	10965	First Draw	Tap	Room 116	TB	08/10/2018	
37.	10966	First Draw	Bubbler	Room 115	3	08/10/2018	
38.	10967	First Draw	Tap	Room 115	5	08/10/2018	
39.	10968	First Draw	Bubbler	Next to Room 115	5	08/10/2018	
40.	10969	First Draw	Tap	Library Workroom	35	08/15/2018	Very yellow water
41.	10970	First Draw		Emergency water	53*	08/15/2018	
42.	10971	Blank		Near back entrance	<1	08/10/2018	04226

*The department of health was notified after testing that this fixture is a non-potable and therefore is not utilized for consumption.