



Lead Sample Collection Information

DISCLAIMER: Results posted here only represent testing done by the Washington State Department of Health for the 2018-19 lead in school drinking water program. Schools have been provided these results, along with recommendations for remediation if applicable. Please contact your school to find out more about this and other testing they may have done, as well as plans for remediation.

Please note: The school has since notified the Department of Health that all fixtures higher than 1ppb were replaced and will be participating in further testing.

School District Name: Lakewood School District

School Name: Lakewood Elementary

School Code: 3255

Address: 17000 16th Dr NE Marysville WA 98271

Number of Samples Collected: 46

Date Collected: 5/10/2018

Sample number	Sample ID	Sample Type	Fixture Description	Fixture Location	Lead Content (ppb)	Date of Analysis	Notes/Comments
Sample 1	9249	First Draw	Tap	Nurse's Office	<1	08/20/2018	
Sample 2	9250	First Draw	Drinking Fountain, Left-side	Red Foyer Drinking Fountain	<1	08/20/2018	
Sample 3	9251	First Draw	Drinking Fountain, Right-side	Red Foyer Drinking Fountain	<1	08/20/2018	
Sample 4	9252	First Draw	Tap	Kitchen	47	08/20/2018	Food Prep Sink
Sample 5	9253	First Draw	Drinking Fountain, Left-side	Kindergarten Pod	<1	08/20/2018	
Sample 6	9254	First Draw	Drinking Fountain, Right-side	Kindergarten Pod	<1	08/20/2018	
Sample 7	9255	First Draw	Bubbler	Room 111	4	08/20/2018	
Sample 8	9256	First Draw	Tap	Room 111	<1	08/20/2018	
Sample 9	9257	First Draw	Bubbler	Room 113	1	08/20/2018	
Sample 10	9258	First Draw	Tap	Room 113	1	08/20/2018	
Sample 11	9259	First Draw	Bubbler	200 Pod	<1	08/20/2018	
Sample 12	9260	First Draw	Tap	200 Pod	<1	08/20/2018	
Sample 13	9261	First Draw	Bubbler	Room 204	<1	08/20/2018	
Sample 14	9262	First Draw	Tap	Room 204	<1	08/20/2018	
Sample 15	9263	First Draw	Bubbler	Room 203	<1	08/20/2018	
Sample 16	9264	First Draw	Tap	Room 203	<1	08/20/2018	
Sample 17	9265	First Draw	Bubbler	Room 202	<1	08/20/2018	
Sample 18	9266	First Draw	Tap	Room 202	<1	08/20/2018	
Sample 19	9267	First Draw	Bubbler	Room 201	4	08/20/2018	
Sample 20	9268	First Draw	Tap	Room 201	<1	08/20/2018	
Sample 21	9269	First Draw	Bubbler	Room 104	<1	08/20/2018	

Sample number	Sample ID	Sample Type	Fixture Description	Fixture Location	Lead Content (ppb)	Date of Analysis	Notes/Comments
Sample 22	9270	First Draw	Tap	Room 104	1	08/20/2018	
Sample 23	9271	First Draw	Bubbler	Room 108	<1	08/20/2018	
Sample 24	9272	First Draw	Tap	Room 108	<1	08/20/2018	
Sample 25	9273	First Draw	Bubbler	Room 107	<1	08/20/2018	
Sample 26	9274	First Draw	Tap	Room 107	<1	08/20/2018	
Sample 27	9275	First Draw	Bubbler	Room 105	<1	08/20/2018	
Sample 28	9276	First Draw	Tap	Room 105	<1	08/20/2018	
Sample 29	9277	First Draw	Tap	Room 117	1	08/20/2018	
Sample 30	9278	First Draw	Bubbler	Room 304	3	08/20/2018	
Sample 31	9279	First Draw	Tap	Room 304	4	08/20/2018	
Sample 32	9280	First Draw	Bubbler	Room 306	40	08/20/2018	
Sample 33	9281	First Draw	Tap	Room 306	33	08/20/2018	
Sample 34	9282	First Draw	Bubbler	Room 307	4	08/20/2018	
Sample 35	9283	First Draw	Tap	Room 307	8	08/20/2018	
Sample 36	9284	First Draw	Bubbler	Room 308	2	08/20/2018	Used by staff that morning
Sample 37	9285	First Draw	Tap	Room 308	2	08/20/2018	
Sample 38	9356	First Draw	Bubbler	Room 309	5	08/20/2018	
Sample 39	9357	First Draw	Tap	Room 309	6	08/20/2018	Some calcification
Sample 40	9358	First Draw	Bubbler	Backroom 309	42	08/20/2018	
Sample 41	9359	First Draw	Bubbler	Room 310	2	08/20/2018	
Sample 42	9360	First Draw	Tap	Room 310	5	08/20/2018	
Sample 43	9361	First Draw	Bubbler	Room 403	<1	08/20/2018	

Sample number	Sample ID	Sample Type	Fixture Description	Fixture Location	Lead Content (ppb)	Date of Analysis	Notes/Comments
Sample 44	9362	First Draw	Tap	Room 403	1	08/20/2018	
Sample 45	9363	First Draw	Bubbler	Room 402	<1	08/20/2018	
Sample 46	9364	First Draw	Tap	Room 402	2	08/20/2018	
Sample 47	9365	First Draw	Blank		<1	08/20/2018	
Sample 49	Notes:	Room 305 not tested because sink had not been used for 2 weeks due to backups					