



Lead Sample Collection Information

School District Name: Boisfort School District

School Name: Boisfort Elementary School

School Code: 2516

Address: 983 Boistfort Rd Curtis, WA 98538

Number of Samples Collected: 22

Date Collected: 2/7/2018

Sample number	Sample ID	Sample Type	Fixture Description	Fixture Location	Lead Content (ppb)	Date of Analysis	Notes/Comments
Sample 1	1501	First Draw	Tap	Kitchen	4	02/16/2018	Under window, right-hand tap used for cooking
Sample 2	1502	First Draw	Bubbler	Cafeteria	9	02/16/2018	
Sample 3	1503	First Draw	Bubbler	Gym/Locker Room	1	02/16/2018	Boy's Locker Room
Sample 4	1504	First Draw	Bubbler	Gym/Locker Room	3	02/16/2018	Girl's Locker Room
Sample 5	1505	First Draw	Bubbler	Room 21	1	02/17/2018	
Sample 6	1506	First Draw	Tap	Room 21	11	02/17/2018	
Sample 7	1507	First Draw	Bubbler	Across from Room 22	<1	02/17/2018	
Sample 8	1508	First Draw	Bubbler	Room 23	5	02/17/2018	
Sample 9	1509	First Draw	Tap	Room 23	<1	02/17/2018	
Sample 10	1510	First Draw	Bubbler	Office	6	02/17/2018	
Sample 11	1511	First Draw	Tap	Office	3	02/17/2018	
Sample 12	1512	First Draw	Bubbler	Room 26	4	02/17/2018	
Sample 13	1513	First Draw	Tap	Room 26	6	02/17/2018	
Sample 14	1514	First Draw	Bubbler	Room 27	7	02/17/2018	
Sample 15	1515	First Draw	Tap	Room 27	2	02/17/2018	

Sample number	Sample ID	Sample Type	Fixture Description	Fixture Location	Lead Content (ppb)	Date of Analysis	Notes/Comments
Sample 16	1516	First Draw	Bubbler	Between Rm. 27 and Rm. 28	<1	02/17/2018	
Sample 17	1517	First Draw	Bubbler	Room 28	2	02/17/2018	
Sample 18	1518	First Draw	Tap	Room 28	2	02/17/2018	
Sample 19	1519	First Draw	Bubbler	Room 29	10	02/17/2018	
Sample 20	1520	First Draw	Tap	Room 29	24	02/17/2018	
Sample 21	1521	First Draw	Bubbler	Room 30	TB		Sink was wet, tap had a slow drip
Sample 22	1522	First Draw	Tap	Room 30	TB		Sink was wet, tap had a slow drip