



Office of Environmental Public Health Sciences  
Washington State Department of Health  
243 Israel Road Southeast, Tumwater Washington 98501

## Lead Sample Collection Information

**DISCLAIMER:** Results posted here only represent testing done by the Washington State Department of Health for the 2018-19 lead in school drinking water program. Schools have been provided these results, along with recommendations for remediation if applicable. Please contact your school to find out more about this and other testing they may have done, as well as plans for remediation.

Please note: The school is following recommended remediation to help reduce children's exposure to lead in drinking water including fixture replacement.

**School District:** North Thurston

**School Name:** Seven Oaks Elementary

**School Code:** 4368

**School Address:** 1800 7 Oaks Rd SE, Lacey Washington 98503

**Number of Samples Collected:** 79

**Date Collected:** 11/21/2019

Program ID	Sample Type	Description	Location	Lead Results (ppb)	Analysis Date	Comments
28979	FirstDraw	other	Blank	<1	12/05/2019	
28981	FirstDraw	Tap	PTA room	3	12/05/2019	
28981	FirstDraw	Tap	Staff work room	3	12/05/2019	
28982	FirstDraw	Bubbler	Multi-use room bubbler adjacent to kitchen	1	12/05/2019	
28983	FirstDraw	Tap	Kitchen double sink	1	12/05/2019	Was dripping on arrival: droplets in sink
28984	FirstDraw	Tap	Kitchen triple sink left tap	6	12/05/2019	
28985	FirstDraw	Tap	Kitchen triple sink middle tap	6	12/05/2019	
28986	FirstDraw	Tap	Kitchen sink rightmost faucet with dishwashing attachment	2	12/05/2019	
28987	FirstDraw	Bubbler	Multi use room bubbler/bottle combo	<1	12/05/2019	
28988	FirstDraw	BottleFiller	Multi use room bubbler/bottle combo	<1	12/05/2019	
28989	FirstDraw	Bubbler	Next to rm 14 downstairs	<1	12/05/2019	
28990	FirstDraw	Tap	Rm 12 workroom	4	12/05/2019	
28991	FirstDraw	Tap	Rm 1	1	12/05/2019	
28992	FirstDraw	Bubbler	Rm 1	<1	12/05/2019	
28993	FirstDraw	Tap	Rm 2	5	12/05/2019	
28994	FirstDraw	Bubbler	Rm 2	<1	12/05/2019	

(continued)

Program ID	Sample Type	Description	Location	Lead Results (ppb)	Analysis Date	Comments
28995	FirstDraw	Tap	Rm 3	<1	12/05/2019	
28996	FirstDraw	Bubbler	Rm 3	<1	12/05/2019	
28997	FirstDraw	Tap	Rm 4	4	12/05/2019	
28998	FirstDraw	Bubbler	Rm 4	<1	12/05/2019	
28999	FirstDraw	Tap	Rm 5	<1	12/05/2019	
29000	FirstDraw	Bubbler	Rm 5	<1	12/05/2019	
29001	FirstDraw	Bubbler	Rm 6	<1	12/05/2019	Leaks from bottom
29002	FirstDraw	Tap	Rm 6	1	12/05/2019	Water present in sink upon arrival
29003	FirstDraw	Tap	Rm 7	9	12/05/2019	
29004	FirstDraw	Bubbler	Rm 7	<1	12/05/2019	Minor leak from bottom
29005	FirstDraw	Tap	Rm 11	4	12/05/2019	
29006	FirstDraw	Bubbler	Rm 11	<1	12/05/2019	
29007	FirstDraw	Tap	Rm 8	6	12/05/2019	
29008	FirstDraw	Bubbler	Rm 8	<1	12/05/2019	
29009	FirstDraw	Tap	Rm 9	6	12/05/2019	
29010	FirstDraw	Bubbler	Rm 9	<1	12/05/2019	
29011	FirstDraw	Tap	Nurse station	2	12/05/2019	
29012	FirstDraw	Tap	Rm 50	1	12/05/2019	
29013	FirstDraw	Bubbler	Rm 50	<1	12/05/2019	
29014	FirstDraw	Tap	Rm 51	1	12/05/2019	Faucet leaking
29015	FirstDraw	Bubbler	Rm 51	<1	12/05/2019	
29016	FirstDraw	Tap	Rm 56 left tap	3	12/05/2019	
29017	FirstDraw	Tap	Rm 56 middle tap	16	12/05/2019	
29018	FirstDraw	Bubbler	Rm 56 middle sink bubbler	11	12/07/2019	

(continued)

Program ID	Sample Type	Description	Location	Lead Results (ppb)	Analysis Date	Comments
29019	FirstDraw	Tap	Rm 56 rightmost tap	5	12/05/2019	
29020	FirstDraw	Tap	Rm 55 kitchen	7	12/05/2019	
29021	FirstDraw	Tap	Rm 57 left tap	6	12/05/2019	
29022	FirstDraw	Tap	Rm 57 middle tap	3	12/05/2019	
29023	FirstDraw	Tap	Rm 57 rightmost tap	6	12/05/2019	
29024	FirstDraw	Tap	Rm 58 left tap	21	12/05/2019	
29025	FirstDraw	Tap	Rm 58 middle tap	18	12/05/2019	
29026	FirstDraw	Tap	Rm 58 right most tap	16	12/05/2019	
29027	FirstDraw	Tap	Rm 33	3	12/05/2019	
29028	FirstDraw	Bubbler	Rm 33	<1	12/05/2019	
29029	FirstDraw	Tap	Rm 34	7	12/05/2019	
29030	FirstDraw	Bubbler	Rm 34	<1	12/05/2019	
29031	FirstDraw	Tap	Rm 35	7	12/05/2019	
29032	FirstDraw	Bubbler	Rm 35	<1	12/05/2019	
29033	FirstDraw	Tap	Rm 36	4	12/05/2019	
29034	FirstDraw	Bubbler	Rm 36	<1	12/05/2019	
29035	FirstDraw	Tap	Rm 37	1	12/05/2019	
29036	FirstDraw	Bubbler	Rm 37	<1	12/05/2019	
29037	FirstDraw	Tap	Rm 38	7	12/05/2019	
29038	FirstDraw	Bubbler	Rm 38	<1	12/05/2019	
29039	FirstDraw	Tap	Rm 39	3	12/05/2019	
29040	FirstDraw	Bubbler	Rm 39	<1	12/05/2019	
29041	FirstDraw	Tap	Rm 40	<1	12/05/2019	
29042	FirstDraw	Bubbler	Rm 40	<1	12/05/2019	
29043	FirstDraw	Tap	Rm 41	7	12/05/2019	
29044	FirstDraw	Bubbler	Rm 41	<1	12/05/2019	

(continued)

Program ID	Sample Type	Description	Location	Lead Results (ppb)	Analysis Date	Comments
29045	FirstDraw	Tap	Portable room 1	1	12/05/2019	
29046	FirstDraw	Bubbler	Portable room 1	<1	12/05/2019	
29047	FirstDraw	Tap	Portable room 2	12	12/06/2019	
29048	FirstDraw	Bubbler	Portable room 2	7	12/06/2019	
29049	FirstDraw	Tap	Portable room 3	2	12/06/2019	
29050	FirstDraw	Bubbler	Portable room 3	<1	12/06/2019	
29051	FirstDraw	Tap	Portable rm 4	3	12/06/2019	
29052	FirstDraw	Bubbler	Portable rm 4	3	12/06/2019	Low pressure; sample taken from dripping down side
29053	FirstDraw	Tap	Portable rm 5	2	12/06/2019	
29054	FirstDraw	Bubbler	Portable rm 5	<1	12/06/2019	
29055	FirstDraw	Tap	Portable rm 6	6	12/06/2019	
29056	FirstDraw	Bubbler	Portable rm 6	1	12/06/2019	
29057	FirstDraw	Bubbler	Bubbler across from restrooms near custodial rm 18	1	12/06/2019	