



Lead Sample Collection Information

DISCLAIMER: Results posted here only represent testing done by the Washington State Department of Health for the 2018-19 lead in school drinking water program. Schools have been provided these results, along with recommendations for remediation if applicable. Please contact your school to find out more about this and other testing they may have done, as well as plans for remediation.

School District Name: Columbia (Walla Walla) School District

School Name: Columbia Elementary School

School Code: 3616

Address: 755 Maple St. Walla Walla WA

Number of Samples Collected: 99323

Date Collected: 5/4/2018

Sample number	Sample ID	Sample Type	Fixture Description	Fixture Location	Lead Content (ppb)	Date of Analysis	Notes/Comments
Sample 1	6550	First Draw	BLANK	BLANK	<1	08/10/2018	
Sample 2	6551	First Draw	Tap	Room 127	5	08/10/2018	
Sample 3	6552	First Draw	Bubbler	Room 127	<1	08/10/2018	
Sample 4	6553	First Draw	Tap	Room 126	2	08/10/2018	
Sample 5	6554	First Draw	Bubbler	Room 126	<1	08/10/2018	
Sample 6	6555	First Draw	Tap	Room 125	1	08/10/2018	
Sample 7	6556	First Draw	Bubbler	Room 125	<1	08/10/2018	
Sample 8	6557	First Draw	Bubbler	Near Room 125	<1	08/10/2018	
Sample 9	6558	First Draw	Tap	Room 124	1	08/10/2018	
Sample 10	6559	First Draw	Bubbler	Room 124	<1	08/10/2018	
Sample 11	6560	First Draw	Tap	Room 118	TB		
Sample 12	6561	First Draw	Bubbler	Room 118	<1	08/10/2018	
Sample 13	6562	First Draw	Tap	Room 119	TB		Left Sink

Sample number	Sample ID	Sample Type	Fixture Description	Fixture Location	Lead Content (ppb)	Date of Analysis	Notes/Comments
Sample 14	6563	First Draw	Bubbler	Room 119	<1	08/10/2018	Left Sink
Sample 15	6564	First Draw	Tap	Room 119	TB		Right Sink - Near Door
Sample 16	6565	First Draw	Bubbler	Room 119	1	08/10/2018	Right Sink - Near Door
Sample 17	6566	First Draw	Tap	Room 117	<1	08/10/2018	
Sample 18	6567	First Draw	Bubber	Room 117	<1	08/10/2018	
Sample 19	6568	First Draw	Tap	Room 116	1	08/10/2018	
Sample 20	6569	First Draw	Bubbler	Room 116	<1	08/10/2018	
Sample 21	6570	First Draw	Bubbler	Near Room 116	<1	08/10/2018	
Sample 22	6571	First Draw	Bottle Filler	Near Room 116	1	08/10/2018	
Sample 23	6572	First Draw	Tap	Room 115	1	08/10/2018	
Sample 24	6573	First Draw	Bubbler	Room 115	<1	08/10/2018	
Sample 25	6574	First Draw	Tap	Kitchen	9	08/10/2018	Main Sink. Furthest Left, Closest to the Wall
Sample 26	6575	First Draw	Tap	Kitchen	3	08/10/2018	Main Sink. Middle Left Tap

Sample number	Sample ID	Sample Type	Fixture Description	Fixture Location	Lead Content (ppb)	Date of Analysis	Notes/Comments
Sample 27	6576	First Draw	Tap	Kitchen	5	08/10/2018	Main Sink. Farthest Right Tap Closest to The Door
Sample 28	6577	First Draw	Tap	Kitchen	2	08/10/2018	Personal Handwashing Sink in the Back, Near Back Exit
Sample 29	6578	First Draw	Tap	Kitchen	TB		Pot Filler, Middle of the Room
Sample 30	6579	First Draw	Tap	Room 114	4	08/10/2018	
Sample 31	6580	First Draw	Bubbler	Room 114	2	08/10/2018	
Sample 32	6581	First Draw	Tap	Room 113	2	08/10/2018	
Sample 33	6582	First Draw	Bubbler	Room 113	1	08/10/2018	
Sample 34	6583	First Draw	Tap	Room 101	2	08/10/2018	
Sample 35	6584	First Draw	Bubbler	Room 101	<1	08/10/2018	
Sample 36	6585	First Draw	Tap	Room 102	1	08/10/2018	
Sample 37	6586	First Draw	Bubbler	Room 102	<1	08/10/2018	
Sample 38	6587	First Draw	Tap	Room 112	3	08/10/2018	
Sample 39	6588	First Draw	Bubbler	Room 112	2	08/10/2018	

Sample number	Sample ID	Sample Type	Fixture Description	Fixture Location	Lead Content (ppb)	Date of Analysis	Notes/Comments
Sample 40	6589	First Draw	Tap	Room 111	2	08/10/2018	
Sample 41	6590	First Draw	Bubbler	Room 111	<1	08/10/2018	
Sample 42	6591	First Draw	Tap	Room 110	4	08/10/2018	
Sample 43	6592	First Draw	Bubbler	Room 110	1	08/10/2018	
Sample 44	6593	First Draw	Tap	Room 107	3	08/10/2018	
Sample 45	6594	First Draw	Bubbler	Room 107	1	08/10/2018	
Sample 46	6595	First Draw	Tap	Room 103	4	08/10/2018	Sink Near Bathroom
Sample 47	6596	First Draw	Bubbler	Room 103	1	08/10/2018	Sink Near Bathroom
Sample 48	6597	First Draw	Tap	Room 103	5	08/10/2018	Sink Near Hallway Wall
Sample 49	6598	First Draw	Bubbler	Room 103	1	08/10/2018	Sink Near Hallway Wall
Sample 50	6599	First Draw	Tap	Room 104	7	08/10/2018	Sink Near Hallway Wall
Sample 51	6600	First Draw	Bubbler	Room 104	2	08/10/2018	Sink Near Hallway Wall
Sample 52	6601	First Draw	Tap	Room 104	2	08/10/2018	Sink Near Bathroom

Sample number	Sample ID	Sample Type	Fixture Description	Fixture Location	Lead Content (ppb)	Date of Analysis	Notes/Comments
Sample 53	6602	First Draw	Bubbler	Room 104	<1	08/10/2018	Sink Near Bathroom
Sample 54	6603	First Draw	Tap	Near Room 105	3	08/10/2018	
Sample 55	6604	First Draw	Bubbler	Room 105	<1	08/10/2018	
Sample 56	6605	First Draw	Tap	Room 106	2	08/10/2018	
Sample 57	6606	First Draw	Bubbler	Room 106	<1	08/10/2018	
Sample 58	6607	First Draw	Bubbler	Near Room 105	<1	08/10/2018	Between Girls & Boys Bathroom
Sample 59	6608	First Draw	Bubbler	Near Room 110	<1	08/10/2018	Between Girls & Boys Bathroom
Sample 60	6609	First Draw	Tap	Clinic	3	8/11/2018	