



Lead Sample Collection Information

DISCLAIMER: Results posted here only represent testing done by the Washington State Department of Health for the 2018-19 lead in school drinking water program. Schools have been provided these results, along with recommendations for remediation if applicable. Please contact your school to find out more about this and other testing they may have done, as well as plans for remediation.

School District Name: Lynden School District

School Name: Bernice Vossbeck

School Code: 4517

Address: 1301 E Bridgeview Dr Lynden WA 98264

Number of Samples Collected: 63

Date Collected: 4/18/2018

Sample number	Sample ID	Sample Type	Fixture Description	Fixture Location	Lead Content (ppb)	Date of Analysis	Notes/Comments
Sample 1	7271	First Draw	Tap	Kitchen	<1	05/02/2018	Used by staff
Sample 2	7272	First Draw	Sprayer	Kitchen	<1	05/02/2018	Used by staff
Sample 3	7273	First Draw	Tap	Staff Lounge	<1	05/02/2018	A little buildup
Sample 4	7274	First Draw	Water Cooler	Main Office	<1	05/02/2018	
Sample 5	7275	First Draw	Rm. 137, Nurses Room	Tap	<1	05/02/2018	Combined w/eyewash station
Sample 6	7276	First Draw	Tap	P-156	<1	05/02/2018	Portable
Sample 7	7277	First Draw	Tap	P-158	<1	05/02/2018	Portable
Sample 8	7278	First Draw	Tap	P-157	<1	05/02/2018	Portable
Sample 9	7279	First Draw	Bubbler	Room 101	<1	05/02/2018	
Sample 10	7280	First Draw	Tap	Room 101	<1	05/02/2018	
Sample 11	7281	First Draw	Bubbler	Room 102	<1	05/02/2018	
Sample 12	7282	First Draw	Tap	Room 102	<1	05/02/2018	
Sample 13	7283	First Draw	Bubbler	Room 103	<1	05/02/2018	
Sample 14	7284	First Draw	Tap	Room 103	<1	05/02/2018	
Sample 15	7285	First Draw	Bubbler	Room 104	<1	05/02/2018	
Sample 16	7286	First Draw	Tap	Room 104	<1	05/02/2018	
Sample 17	7287	First Draw	Bubbler	Room 105	<1	05/02/2018	
Sample 18	7288	First Draw	Tap	Room 105	<1	05/02/2018	
Sample 19	7289	First Draw	Bubbler	Room 106	<1	05/02/2018	
Sample 20	7290	First Draw	Tap	Room 106	<1	05/02/2018	
Sample 21	7291	First Draw	Bubbler	Room 108	<1	05/02/2018	

Sample number	Sample ID	Sample Type	Fixture Description	Fixture Location	Lead Content (ppb)	Date of Analysis	Notes/Comments
Sample 22	7292	First Draw	Tap	Room 108	<1	05/02/2018	
Sample 23	7293	First Draw	Tap	Southeast Workroom	<1	05/02/2018	Tap dripping; no aerator; some calcification
Sample 24	7294	First Draw	Bubbler	Room 109	<1	05/02/2018	
Sample 25	7295	First Draw	Tap	Room 109	<1	05/02/2018	
Sample 26	7296	First Draw	Bubbler	Room 110	<1	05/02/2018	
Sample 27	7297	First Draw	Tap	Room 110	<1	05/02/2018	
Sample 28	7298	First Draw	Drinking Fountain, Left	Southeast Hall	<1	05/02/2018	Near Room 111
Sample 29	7299	First Draw	Drinking Fountain, Right	Southeast Hall	<1	05/02/2018	Near Room 111
Sample 30	7300	First Draw	Bubbler	Room 111	<1	05/02/2018	
Sample 31	7301	First Draw	Tap	Room 111	<1	05/02/2018	
Sample 32	7302	First Draw	Bubbler	Room 112	<1	05/02/2018	
Sample 33	7303	First Draw	Tap	Room 112	<1	05/02/2018	
Sample 34	7304	First Draw	Bubbler	Room 113	<1	05/02/2018	
Sample 35	7305	First Draw	Tap	Room 113	<1	05/02/2018	
Sample 36	7306	First Draw	Bubbler	Room 114	<1	05/02/2018	
Sample 37	7307	First Draw	Tap	Room 114	<1	05/02/2018	
Sample 38	7308	First Draw	Bubbler	Room 115	<1	05/02/2018	
Sample 39	7309	First Draw	Tap	Room 115	<1	05/02/2018	
Sample 40	7310	First Draw	Drinking Fountain	Gym	<1	05/02/2018	
Sample 41	7311	First Draw	Tap	Library	<1	05/02/2018	White buildup on Tap

Sample number	Sample ID	Sample Type	Fixture Description	Fixture Location	Lead Content (ppb)	Date of Analysis	Notes/Comments
Sample 42	7312	First Draw	Drinking Fountain, Left	Main Hallway	<1	05/02/2018	
Sample 43	7313	First Draw	Drinking Fountain, Right	Main Hallway	<1	05/02/2018	
Sample 44	7314	First Draw	Tap	Room 133	<1	05/02/2018	Calcification on Tap
Sample 45	7315	First Draw	Bubbler	Room 132	<1	05/02/2018	
Sample 46	7316	First Draw	Tap	Room 132	<1	05/02/2018	
Sample 47	7317	First Draw	Bubbler	Room 122	<1	05/02/2018	
Sample 48	7318	First Draw	Tap	Room 122	<1	05/02/2018	
Sample 49	7319	First Draw	Bubbler	Room 123	<1	05/02/2018	
Sample 50	7320	First Draw	Tap	Room 123	<1	05/02/2018	
Sample 51	7321	First Draw	Drinking Fountain, Left	Near Room 123	<1	05/02/2018	
Sample 52	7322	First Draw	Drinking Fountain, Right	Near Room 123	<1	05/02/2018	
Sample 53	7323	First Draw	Bubbler	Room 124	<1	05/02/2018	Very poor flow, bottle not full
Sample 54	7324	First Draw	Tap	Room 124	<1	05/02/2018	A little calcification
Sample 55	7325	First Draw	Bubbler	Room 125	<1	05/02/2018	
Sample 56	7326	First Draw	Tap	Room 125	<1	05/02/2018	
Sample 57	7327	First Draw	Tap	Southwest Workroom	<1	05/02/2018	Aerator missing, calcification on tap
Sample 58	7328	First Draw	Bubbler	Room 128	<1	05/02/2018	
Sample 59	7329	First Draw	Tap	Room 128	<1	05/02/2018	Used by Staff
Sample 60	7330	First Draw	Bubbler	Room 129	<1	05/02/2018	

Sample number	Sample ID	Sample Type	Fixture Description	Fixture Location	Lead Content (ppb)	Date of Analysis	Notes/Comments
Sample 61	7331	First Draw	Tap	Room 129	<1	05/02/2018	
Sample 62	7332	First Draw	Bubbler	Room 130	<1	05/02/2018	
Sample 63	7333	First Draw	Tap	Room 130	<1	05/02/2018	
Sample 64	7334	First Draw	Blank	Room 130	<1	05/02/2018	05841